

重劃小檔案 Files

辦理時間 / Time : 79.4~83.4
 重劃總面積 / Total consolidation area
 120.3502公頃 (hectare)
 提供建築用地面積 / Building area
 72.5515公頃 (hectare)
 重劃總費用 / Total consolidation expenses
 20億2063萬5792元

東：六順路
 East from Liushun Rd.
 西：旱溪東路
 West to Hanxi East Rd.
 南：東英一街為界
 South bordering Dongying First St.
 北：十甲路、精武路南側
 North nearly to Shijia Rd. and the southern part of Jingwu Rd.



第九期旱溪重劃區位於東區，未重劃前小型工廠林立，並因旱溪、大里溪流經，時有水患。重劃後，大里溪經整治，串聯大里區的發展，帶動區域繁榮。

The 9th Hanxi Urban Land Consolidation Plan was located in the East district. Before consolidation, small-scale factories dominated this area but suffered from occasional flooding from Han and Dali rivers. The consolidation plan straightened the Dali River and has boosted local business activities, perfectly complementing developments in Dali district.

重劃後段別名稱：旱清、旱新、旱平

Section names after the consolidation : Hanqing, Hanxin and Hanping



重劃前概況

本重劃區位於東區，原為工業區，地籍零亂、工廠林立，環境衛生極差，另旱溪、大里溪橫跨其間、時有水患。

Pre-consolidation summary

This consolidation area, located in the East district, was an industrial park with a great number of factories. The cadastre system was in disarray and public health was below standards. In addition, the Han and Dali rivers crisscrossed the area, causing occasional flooding.